

March 30<sup>th</sup>, 2011

Tokyo Big Sight Inc.

**Impact of Tohoku Pacific Earthquake on Tokyo Big Sight Facilities**

We offer our heartfelt prayers to all those who tragically lost their lives in the March 11th Tohoku Pacific Earthquake, as well as our sympathy to the survivors and their families.

Tokyo Big Sight (Tokyo International exhibition Center) facilities received no major damage during the recent earthquake. Recent detailed information is provided below, and information will be updated as needed.

**1. Utilities**

No damage was observed to electricity, gas, communication, and water supplies.

**2. Transportation facilities (lift and escalator)**

Safety inspections were performed on all transportation facilities, confirming that they are operating normally.

**3. Exhibition Halls**

No major functional damage was observed. Partial malfunction occurred with some hall partitions and shutters.

**4. Other**

No liquefaction was observed in the Tokyo Big Sight premises or surrounding area, including parking lots.

To further ensure safety of visitors, we are now performing safety checks and treatments inside and outside of the buildings once again. In addition, no major damage, fire, or any other disaster was found in surrounding facilities.

(Reference) Current status of Tokyo Big Sight (Tokyo International exhibition Center)  
(Photos taken on March 18th, 2011)

## 1. Entrance hall



## 2. Parking lots beside east building




## 3. East Exhibition Hall

### (1) View of Galleria



### (2) Inside view of exhibition halls



## 4. West Exhibition Hall

### (1) View of Atrium



### (2) Inside view of exhibition halls

